NOTICE OF AN APPLICATION FOR PLANNING PERMIT

The land affected by the application is located at:	Lot 10 LP6949 18 Amphlett Avenue, Cockatoo							
The application is for a permit to:	Development of the land for a dwelling and vegetation removal							
The applicant for the permit is:	MAP Building Consultant Services							
The application reference number is:	T170025							
You may look at the application and any documents that support the application at the office of the Responsible Authority:	Cardinia Shire Council 20 Siding Avenue Officer 3809 This can be done during office hours and is free of charge. Documents can also be viewed on Council's website www.cardinia.vic.gov.au.							

Any person who may be affected by the granting of the permit may object or make other submissions to the responsible authority.

An objection must	*		sent ardinia S <u>@cardinia</u>			Responsible PO Box 7, Paker	•	in 310 or	writing, email at
	*	inclu	de the na	ame a	nd add	ress of the objecto	or/ submitter		
	*	inclu	de the a	pplicat	ion nu	mber and site add	ress		

*	state how the objector would be affected.

include the reasons for the objection, and

The Responsible Authority will not decide on the application before:	10 May 2017
--	-------------


If you object, the Responsible Authority will advise you of its decision.

Please be aware that copies of objections/submissions received may be made available to any person for the purpose of consideration as part of the planning process.

For additional information or advice contact Cardinia Shire Council, Planning Department on 1300 787 624 or mail@cardinia.vic.gov.au

Your objection/ submission and personal information is collected by Cardinia Shire Council for the purposes of the planning process as set out in the *Planning and Environment Act 1987*. If you do not provide your name and address, Council will not be able to consider your objection/ submission. Your objection/ submission will be available free of charge at the Council office for any person to inspect and copies may be made available on request to any person for the relevant period set out in the *P&E Act*. You must not submit any personal information or copyright material of third parties without their informed consent. By submitting the material, you agree that the use of the material as detailed above does not breach any third party's right to privacy and copyright.





LOT 11

SINGLE STOREY

WEATHERBOARD DWELLING FASCIA AND GUTTER

PROPOSED DRIVEWAY BY CHENT AFTER PANDOVER.

PROPOSED CROSS-OVER BY CLIENT AFTER HAND OVER TO COUNCIL REQUIREMENTS

(Cross Over 3 muche)



DATE	AMENDMENT	BY
26.10.16	ADD FORM 8 POST TENDER (06.10.16) PQ to CON.	RS
26.10.16	ADD SOIL AND SURVEY.	RS
02.11.16	ADD GV DOCS.	RS
22.11.16	ADD PCV01 & AMENDMENT FOR TP.	RS
13.12.16	ADD PCVO 2	SK
19.12.16	AMENDMENTS FOR TOWN PLANNING	EA
23,12,16	TANK NOTES UPDATED	EA

SIMONDS HOMES VICTORIA P/L ACN 050 197 610 HEAD OFFICE 1ST FLOOR 570 ST KILDA ROAD, MELBOURNE VIC 3004

ENQUIRIES 1300 SIMONDS E-MAIL enquiries@simonds.com.gu INTERNET www.simonds.com.au


House: 1:250@A3 16 STANTEN_2814 Pacade: BALTIMORE Drawn: DB RS Job No: 51070 CON Checked: Sheet No:

Ref to Arborist Report for

Trees 1, 2, 3, 4 28 & 29

Width of Canopy of Trees for

View: NEW LIVING RANGE SITE PLAN Customer: (ALFRESCO + DINING OPTION + BUTLERS' OPTION) MS.NICOLE L PHILBRICK & MR.DARREL B BLIGH - DEVELOPMENT DIVISION PURPOSE ONLY -COPYRIGHT 2003 SIMONDS IP Pty Ltd (ACN 144 838 805) (A8N 56 144 839 805) NOT TO BE REPRODUCED IN PART OR WHOLE WITHOUT EXPRESS PERMISSION. LOT 10, 18 AMPHLETT AVENUE, COCKATOO, VIC.




SIMONDS

LOT 13

SINGLE STOREY WEATHERBOARD DWELLING FASCIA AND GUTTER

This copied document is made available for the purpose of the planning process as set out in the Planning and Environment Act 1987. The information must not be used for any other purpose. By taking a copy of this document you acknowledge and agree that you will only use the document for the purpose specified above and that any dissemination, distribution or copying of this document is strictly prohibited.

88*57" 21.34



SIMONDS HOMES VICTORIA P/L ACN 050 197 610 HEAD OFFICE 1ST FLOOR 570 ST KILDA ROAD, MELBOURNE VIC 3004 TELEPHONE (03) 9682 0700

ENQUIRIES 1300 SIMONDS E-MAIL enquiries@simonds.com.au INTERNET www.simonds.com.gu

NEW LIVING RANGE

SITE PLAN

Customer: MS.NICOLE L PHILBRICK & MR.DARREL B BLIGH

1:500@A3

House:

Facade:

Drawn:

DB RS


Checked: STANTEN_2814 **BALTIMORE** Job No: 51070 CON Sheet No: 1.2


(ALFRESCO + DINING OPTION + BUTLERS' OPTION) - DEVELOPMENT DIVISION PURPOSE ONLY -


View:

COPYRIGHT 2003 SIMONDS IP Pty Ltd (ACN 144 839 805) (ABN 56 144 839 805) NOT TO BE REPRODUCED IN PART OR WHOLE WITHOUT EXPRESS PERMISSION.

LOT 10, 18 AMPHLETT AVENUE, COCKATOO, VIC.







26.

Drawn: DB RS


hecked:


Job No: 51070

Sheet No:

CON

3.1





Customer:

Address:

MS.NICOLE L PHILBRICK & MR.DARREL B BLIGH

LOT 10, 18 AMPHLETT AVENUE, COCKATOO, VIC.

(ALFRESCO + DINING OPTION + BUTLERS' OPTION)

- DEVELOPMENT DIVISION PURPOSE ONLY -


COPYRIGHT 2003 SIMONDS IP Pty Ltd (ACN 144 839 805) (ASN 56 144 839 805) NOT TO BE REPRODUCED IN PART OR WHOLE WITHOUT EXPRESS PERMISSION.


TELEPHONE (03) 9682 0700

THE GREAT AUSTRALIAN BUILDER

INTERNET www.simonds.com.gu

SIMONDS







BUSHFIRE MANAGEMENT PLAN

18 AMPHLETT AVENUE, COCKATOO

VERSION B

24 December 2016





BUSHFIRE PROTECTION MEASURES SCHEDULE

18 AMPHLETT AVENUE, COCKATOO

DEFENDABLE SPACE VEGETATION MANAGEMENT

Defendable space of 50m or to the property boundary (whichever is the lesser) to be applied in all directions. Within this area, vegetation must be modified and managed in accordance with the following requirements:

- Grass must be short cropped and maintained during the declared Fire Danger Period
- All leaves and vegetation debris must be removed at regular intervals during the declared Fire Danger Period
- Within 10m of a building, flammable objects must not be located close to the vulnerable parts of the building
- Plants greater than 10cm in height must not be placed within 3m of a window or glass feature of the building.
- · Shrubs must not be located under canopy trees.
- Individual and clumps of shrubs must not exceed 5m² in area and must be separated by at least 5m.
- · Trees must not overhang or touch any elements of the building.
- · The canopy of trees must be separated by at least 5m.
- There must be a clearance of at least 2m between the lowest tree branches and ground level.

WATER SUPPLY FOR FIRE FIGHTING PURPOSES

A water supply with an effective capacity of **10,000 litres** must be established on the site which meets the following requirements:

- · Is stored in an above ground tank constructed of concrete or metal
- All fixed above ground water pipes and fittings required for fire fighting purpose must be made of corrosive resistant metal.
- Incorporate a ball or gate valve (65mm BSP) and coupling (64mm CFA 3 TPI male fitting)
- The outlet of the tank must be within 4m of the access way and be unobstructed.
- Be readily identifiable from the building or appropriate identification signage to the satisfaction of the CFA must be provided.
- Any pipework and fittings from the tank to the remote outlet/riser must be a minimum 100mm,
 Class 12
- The riser pipe and fittings from the feeder pipe to the outlet can be reduced to a minimum 65mm, Class 12 pipe (excluding CFA coupling)
- The centre line of the suction connections shall be located at a height between 450mm and 600mm from the finished ground level
- All below ground pipelines to be installed to at least the following depths:
 - 300mm if subject to vehicle traffic
 - o 75mm under dwellings or concrete slabs
 - o 225mm in all other locations


ACCESS DESIGNED TO ACCOMMODATE CFA ACCESS

- Not required Length of driveway is less than 30m.
- Access to within 4m of the water supply outlet will be provided.

CONSTRUCTION

The dwelling must be designed and constructed to a minimum Bushfire Attack Level of BAL 29 in accordance with AS3959-2009

No construction requirements are being applied to the shed



Map 3 Site Map showing tree location and defendable space

Vegetation Assessment

3.0

Table 1. Tree List at 18 Amphlett Ave, Cockatoo

No.	Species	DBH cm	TPZ m	SRZ m	Hgt~	Wth-	L.S.	Sig.	ULE yrs	Struct	Roots	Сру	R/ Ret	Notes
1	Eucalyptus obliqua (Messmate)	47.7	5.7	2.6	15	8	Mat	High		2	2	3	R	Growing with T2, so intertwined if one is removed they would both be lost, large epicormic on W side, insect and possum damage, low use accessway within TPZ, service line through canopy, has had some pruning – healing well, fissures in bark.
2	Acacia dealbata	38.8	4.7	2.5	13	12	Sen	High	<5	1	2	3	R	Growing with T1, lots of included bark between them, branches rubbing, ivy growing at base and up trunk, some deadwood, branches pruned long ago - healing well, low use accessway within TPZ, service line through canopy, cracks in trunk – exuding sap.
3	Eucalyptus obliqua	58.2	6.9	2.9	18	10	Mat	High	5+	2	1	3	R	Growing with T4- if one is removed they would both be lost, lost apical dominance, has a lignotuberous shoot to the N, lots of sap, fence within SRZ/TPZ.
4	Acacia dealbata (Silver Wattle)	28.6	3.4	2.1	15	7	Mat	High	5+	2	1	3	R	Growing right next to Tree 3 they have included bark together – trunks no more than 30cm apart up higher, some deadwood, some previous pruning, lots of sap, single

														sided – allelopathic effect from T2, exposed SR, fence within SRZ/TPZ.
5	Eucalyptus obliqua	38.2	4.6	2.4	15	4	Sen	High	<5	1	1	2	R	Growing on an island from altered NGL, all canopy is epicormics, lost apical dominance, large scar on E side, trunk ooze, termites & beetles, insect damage to leaves.
6	Eucalyptus obliqua	82.8	9.9	3.4	19	19	Mat	High		1	3	3	R	Bifurcated up high – repeated, burnt S side, lots of large deadwood, dieback from tips, trunk insect galls, exposed large SR, lots of sap, altered NGL.
7	Eucalyptus obliqua	44.6	5.3	2.6	19	7	Sen	High		1	3	3	R	Lost apical dominance, insect galls, lots of sap, majority of canopy is epicormics, lifting bark, insect damage. Recommended
8	Eucalyptus obliqua	105.0	12.6	3.5	20	15	Sen	High	<5	1	2	3	R	Bifurcated 2m up high – rot in included bark, burnt trunk SW side, altered NGL, 80% of canopy is epicormics, insect damage, fissures in bark, sap, fence in SRZ/TPZ, existing impact.
9	Eucalyptus obliqua	68.4	8.2	2.9	18	14	Sen	High	<5	1	3	2	R	Bifurcated up high, lots of large deadwood, bark lifting, fissures in bark, recently lost branches, epicormics, insect damage, fence within SRZ/TPZ.
10	Eucalyptus radiata	35.0	4.2	2.4	15	10	Mat	High		2	2	3	R	Majority of canopy is epicormics, dieback from apical tip – shoots bifurcated around this, NGL altered – inc. large depression in TPZ.
11	Eucalyptus obliqua	39.78+ 50.92=	8.0	3.1	18	8	Sen	High	<5	1	2	1	R	Repeated bifurcation, 1 co- dependant fallen, included bark &

		65.0												shelf fungus in initial bifurcation, large scar W side, termites, lots of deadwood & epicormics, altered NGL.
12	Eucalyptus obliqua	75.0											R	Dead
13	Eucalyptus radiata (Narrow-leaf Peppermint)	31.8	3.8	2.2	14	6	Mat	High	5+	2	4	2	R	Top of T12 has fallen into this tree, recent physical damage, bifurcated up high, insect damage, deadwood, lots of epicormics.
14	Eucalyptus cypellocarpa (Mountain Grey Gum)	106.0	12.7	3.6	20	18	Mat	High	10+	3	4	3	Ret	Lost large limb W side – shelf fungus, large deadwood, insect damage, some epicormics. Rec. Structural and deadwood pruning, monitor.
15	Eucalyptus obliqua	13.5	1.6										R	
16	Eucalyptus cypellocarpa	28.5	3.4										R	
17	Acacia pravissima (Ovens River Wattle)	7	84= 1.5 default										R	
18	Eucalyptus obliqua	62.5	7.5										R	
19	Eucalyptus cypellocarpa	11.5	1.4= 1.5 default										R	
20	Eucalyptus cypellocarpa	40.5	4.9										R	
21	Acacia mucronata (Narrow-leaf	3.5+4.5 +4.5+4 .5=9	1.1= 1.5 default										Ret	

	Wattle)													
22	Acacia mucronata	4+5.5+ 5.5=8	1= 1.5 default										Ret	
23	Eucalyptus cypellocarpa	78.0	9.4	3.1	18	18	Mat	High	5+	2	3	2	Ret	Bifurcated up high - repeated, holly & ivy growing at base, lots of deadwood, insect damage, dieback from tips – thin canopy, disturbance in RZ, fence in SRZ/TPZ.
24	Acacia melanoxylon	11.1	1.3 (2m default)	1.5	6	4	Mat	High	10+	4	4	3	Ret	Reasonable specimen, some deadwood, psyllid infestation, slight lean to E.
25	Eucalyptus cypellocarpa	10	1.2= 1.5Def.										R	
26	Acacia mucronata	13+15 +4.7+ 4.2=21	2.5										Ret	
27	Eucalyptus cypellocarpa	120.0	14.4	3.9	18	18	Mat	High	10+	3	3	4	Ret	Next Door to N. Lots of large epicormics, large scar at base, rope around trunk 2m up, minor deadwood, fence & water tank in SRZ.
28	Eucalyptus macrorhyncha (Red Stringybark)	55.0	6.6	2.8	20	12	Mat	High	5+	2	2	2	Ret	ND – N. Bifurcated up high, allelopathic effect <i>E. obliqua</i> to N, some deadwood, insect damage, fence, services & pond in SRZ/TPZ, should be pruned away from power lines.
29	Eucalyptus obliqua	30.0	3.6	2.1	14	10	Mat	High	<5	1	2	3	Ret	ND – N. lost apical dominance, epicormics, odd branching, allelopathic effect – leaning on fence, insect damage, fence, services & pond in SRZ/TPZ.

Legend:

DBH = Diameter at Breast Height, measured in centimetres, L.O.T. in EVC 16 = 70cm

Hgt = Height, measured in metres

Wth = Width, measured in metres

TPZ = Tree Protection Zone, calculated as 12 x DBH

SRZ = Structural Root Zone => Xm

L.S. = Life stage:

Young

Mat = Mature

Sen = Senescing

Sig. = Significance, assessed as high, moderate or low

ULE = Useful Life Expectancy, estimated in years

Struct. = Structure, scored out of 5 (1=poor to 5=excellent)

Roots = root environment health, scored out of 5

Cpy = Canopy health, scored out of 5

R/Ret = tree proposed to be R=Removed/Ret=Retained

NGL = Natural Ground Level

SR = Structural Roots

ND = Next Door